



2002 Hawker 800XP

Serial Number: 258585 Registration: N585VC

AIRFRAME & ENGINES

Airframe Total Time: 7213.7 Hours
Landings: 4167
Powerplant: Honeywell TFE731-5BR
Engine 1: 6790.6 TSN, 3918 CSN, JSSI
Engine 2: 7025.4 TSN, 4052 CSN, JSSI
APU: Garrett GTCP36-150(W): 4452 Hours
FlightDocs Maintenance Tracking Program
B-RNAV / P-RNAV / RNP-5

AVIONICS

Collins Pro-Line 21 Suite w/ 4 AFD 8" x10" EFIS	Dual TDR-94 Transponders
RTA-858 Weather Radar	Collins HF 9000 w/ SELCAL
Dual Collins VHF-422C Comms w/8.33 Spacing	ADC-3000 Air Data Computers
Dual VIR-432 Navs w/FM Immunity	Dual AHRS-3000 / Meggitt Standby AHRS
TCAS II w/Change 7	Honeywell Mark VII EPGWS
Dual FMS-6000 w/ Version 3.0.3 Upgrade	Dual DME-442
w/ Dual GPS 4000A	

INTERIOR

Three Crew + Nine Passengers, Four-Place Club Fwd Seating, Three-Place Divan Aft-Cabin Opp One Club, Chair Jumpseat, Sand Leather Seating, Wool-blend Carpet, Medium Wood Finishing, Nickel-Plated Fixtures, Dual 15" Monitors, Airshow 400 Passenger In-Flight Information, DVD & CD Players, 115 VAC Outlets, Forward, Illuminated Galley Microwave, Beverage Storage, Belted Aft Lavatory Lighted Sink and Mirror

EXTERIOR

Duncan Aviation: July 2015 -- Overall Matterhorn White with Royal Blue on bottom half of fuselage, with Royal Blue and Yellow Striping

ADDITIONAL EQUIPMENT

406 MHz EL T w/Navigation Interface
API Winglets
3rd Long Range Oxygen Bottle

MAINTENANCE STATUS

B inspection last c/w @ 6,755.5 ACTT next due @ 7,555.5 ACTT (800 hours)
C inspection last c/w @ 7,200.1 ACTT next due @ 8,800.1 ACTT (1600 hours)
D inspection last c/w @ 5,620.3 ACTT next due @ 8,820.3 ACTT (3200 hours)
E inspection c/w 09/17 (12 month)
F inspection c/w 09/17 (24 month)
G inspection c/w 09/17 (48 month)
15-Year Structural Inspection c/w 09/17